


Improvement to road No. 11, West of Churaveshwari nagara
at Bagalkote



Index

→ work spot

→ sketch is not to scale

EXECUTIVE ENGINEER

Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Shree
BANGALORE
MUNICIPALITY
BANGALORE
BANGALORE

Audited and admitted for Rs. **5014674-20**
 Passed by Cheque for No. **4849600** M. A. R. 57 (Rule 116)
 Serial No.
 Name of work **168094-20**
 Name of Contractor of Nature of Agency **From** To
 Date of completion of work
 Date of Accounts Submission **Ex. Engineer.**

No. D 60731

1	2	3	Dimensions			7	8
			Number	Length	Breadth	Depth	Contents Reference to last Measurement
certificates ① The work is completed by contractor satisfactorily ② The contractor has removed all debris from work spot ③ There is no departmental issues made by contractor.							

contractor sign
54/12/18
Signature
Inspector, District
Signature
Inspector, District